

22 June 1969

MEMORANDUM FOR: Director, PIC

THROUGH: Deputy Director, PIC
THROUGH: Executive Officer, PIC

SUBJECT: Safety; Grounding of Electrical Appliances

1. [redacted] drew attention to the fact that the 3rd prong of the grounding plugs of the light tables had been clipped and were no longer useable. He further stated that these grounding connections were so placed to prevent personnel accidents and that they should be used.

STAT

2. It is recommended that all new receptacles placed in the building be of the type to accept 3-prong ground type plugs. It is further recommended that all existing receptacles be grounded by use of a "cheater" receptacle and the "pigtail" ground wire be attached as prescribed. Every piece of equipment in PIC should be immediately inspected for proper grounding and the equipment be disconnected until proper grounding has been instituted. This action should take place before an unfortunate accident occurs.

STAT

CC: [redacted]

STAT

FOR CLOSING